






C-TRF 18




ST 18



PVC




 $Z = 120 \text{ mm} - 140 \text{ mm}$

max 90 mm






2a




PTH / PFE

PCP
L = 1400 mmPCP
W = 1340 mm


2b




3




4




5




6




7




8



9








10


4x 30 mm

Four screws are shown, with a dimension line indicating a length of 30 mm.










PCP






11a




PTH/PFE




11b




12




13




14




15




16




17




18








19




21



20





! A = B








22

23


8x  30 mm

24


12x  60 mm




28




29




30




31




32










33




34







41



42



