












C TRF 100

C TRF 50




 $Z = 120 \text{ mm} - 140 \text{ mm}$



max 90 mm




i




Q_{ty}	W_A
2	$(2 * W) + S + 40 \text{ mm}$
3	$(3 * W) + (2 * S) + 40 \text{ mm}$
X	$(X * W) + ((X - 1) * S) + 40 \text{ mm}$




2a




2b




3




4




5




6




7




8




9




10








11



12






17

8x


30 mm




2x





18




19














23





24









31



32a



32b






C TRF 100

S = 100 mm

33a

4x  30 mm




C TRF 50

S = 50 mm

33b

4x  30 mm



34



35

